

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
MASS,
9-WATO,
5G-

Watertown Arsenal
Building # 313
Arsenal Street
Watertown
Middlesex County
Massachusetts

HAER # MA-20-G

Jet Lowe, Photographer August 1982

MA-20-G-1	SOUTH AND EAST ELEVATIONS, LOOKING NORTHWEST
MA-20-G-2	WEST AND SOUTH ELEVATIONS, LOOKING NORTHWEST
MA-20-G-3	INTERIOR
MA-20-G-4	INTERIOR, DETAILING SHOWING EXPOSED WOOD ROOF TRUSS

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
MASS
9-WATO
5G-

Addendum to:
Watertown Arsenal, Building No. 313
(Carriage and Machine Shop)
Talcott Avenue
Watertown
Middlesex County
Massachusetts

HAER No. MA-20-G
(Page 2)


Photographer: Robert Brewster
Warren Jagger Photography, Inc.
150 Chestnut Street
Providence, Rhode Island 02906

June 1991

Four photographs were previously submitted to the Library of Congress.

- | | |
|------------|---|
| MA-20-G-5 | West and north elevations, looking southeast. |
| MA-20-G-6 | Detail, of two remaining original window openings (blocked) and sills, south elevation. |
| MA-20-G-7 | Interior, 313 Center, west gable end of powerhouse section and 1918 Charpy Stress Test Machine, looking west. |
| MA-20-G-8 | Interior, 313 North, typical space, looking northwest. |
| MA-20-G-9 | Interior, 313 North basement, well in south wall, looking southeast. |
| MA-20-G-10 | Historic photograph, April 9, 1968. West and south elevations, looking northeast. U. S. Army Photograph: Corps of Engineers, New England Division. File Number 844. (Copies located at U.S. Army Corps of Engineers, New England Division, Waltham, Massachusetts; and Historical Files, Public Affairs Office, AMTL, Watertown). |
| MA-20-G-11 | Photocopy of drawing, May 22, 1919. Machine Shop ALTERATIONS, EAST WING, FIRST AND SECOND FLOOR PLANS AND SECTION. Watertown Arsenal Engineering Division. Drawing Number 9222. (Original: AMTL Engineering Division, Watertown). |

ADDENDUM TO
WATERTOWN ARSENAL, BUILDING No. 313
(Carriage and Machine Shop)
HAER No. MA-20-G
Key to Photographs
(Page 3)



Source: E. G. & G., USATHAMA report, 1968.